

What You Can Expect:



Radon Levels Before and After Mitigation

| Install Date | Year Home Built | Address | City | Type of Mitigation | Pre-Mitigation Result | Post-Mitigation Result |
|--------------|-----------------|-------------------------------|--------------|--------------------|-----------------------|------------------------|
| Dec-18 | 1991 | Finch Lane | Mound | DTD | 9.0 | 0.1 |
| Oct-19 | 1997 | Hilcrest Dr | Stacy | DTD | 1.0 | 0.1 |
| May-18 | 2008 | Finlay Bay N | Hugo | DTD | 1.2 | 0.2 |
| Jun-18 | 2014 | 87 th St NE | Monticello | DTD | 15.0 | 0.2 |
| Dec-18 | 1996 | Xkimo Ct NW | Ramsey | DTD | 3.5 | 0.2 |
| Feb-20 | 1982 | 21th Ave NW | Oak Grove | SSD | 2.5 | 0.2 |
| Jan-18 | 1983 | West 110 th Street | Bloomington | SSD | 5.5 | 0.3 |
| Jan-18 | 1996 | Acorn Circle | Rockford | DTD | 3.5 | 0.3 |
| Feb-18 | 1971 | Juniper Ridge Dr | Ramsey | SSD/SMD | 6.1 | 0.3 |
| Feb-18 | 1930 | Victory Mem. Dr. | Minneapolis | SSD | 4.0 | 0.3 |
| Mar-18 | 2000 | 43 rd St NW | St. Michael | DTD | 6.1 | 0.3 |
| Mar-18 | 1979 | Rum River Dr | Anoka | SSD | 4.9 | 0.3 |
| Mar-18 | 1917 | Sheridan Ave S | Minneapolis | SSD | 4.1 | 0.3 |
| Mar-18 | 1916 | 12 th Ave S | Minneapolis | SSD | 1.5 | 0.3 |
| Apr-18 | 1975 | 146th St NW | Elk River | DTD | 9.0 | 0.3 |
| Apr-18 | 1984 | 10 th St NE | St Michael | SSD | 11.0 | 0.3 |
| Apr-18 | 1867 | Madison St | Anoka | SSD | 10.0 | 0.3 |
| Apr-18 | 2004 | Orleans LN N | Champlin | DTD | 7.5 | 0.3 |
| Apr-18 | 2018 | Empire LN N | Plymouth | DTD | 7.0 | 0.3 |
| Apr-18 | 1960 | Morris Rd | Bloomington | SSD | 6.4 | 0.3 |
| Apr-18 | 1992 | Gypsy Valley Rd | Nowthen | DTD | 5.8 | 0.3 |
| May-18 | 2004 | Zircon LN N | Maple Grove | DTD | 3.9 | 0.3 |
| Jun-18 | 1978 | Lanewood LN N | Maple Grove | DTD/SSD | 4.5 | 0.3 |
| Jul-18 | 1988 | 285 th Ave NE | Isanti | DTD | 14.0 | 0.3 |
| Sep-18 | 1963 | 69 th Ave NE | Fridley | SSD | 5.2 | 0.3 |
| Oct-18 | 1973 | Vinewood LN N | Dayton | SSD | 6.7 | 0.3 |
| Oct-18 | 1965 | Morton Ave NW | Elk River | SSD | 3.8 | 0.3 |
| Nov-18 | 2008 | 54 th St NE | Otsego | DTD | 25.0 | 0.3 |
| Dec-18 | 2013 | Nokomis Ave | Minneapolis | DTD | 4.6 | 0.3 |
| Dec-18 | 2014 | 197 th St W | Lakeville | DTD | 4.1 | 0.3 |
| Jan-19 | 1995 | 39 th Place N | Plymouth | DTD | 6.7 | 0.3 |
| Feb-19 | 2019 | Weaver Lake Rd | Maple Grove | DTD | 4.0 | 0.3 |
| Apr-19 | 1919 | Elliot Ave | Minneapolis | SSD | 4.7 | 0.3 |
| Apr-19 | 2005 | 78 th Ct N | Maple Grove | DTD | 4.5 | 0.3 |
| May-19 | 1993 | Liberty Lane | Chisago City | DTD | 16.5 | 0.3 |
| May-19 | 1993 | 154 th Ln NW | Ramsey | SSD | 3.1 | 0.3 |
| Jun-19 | 2007 | Everton Ave N | Forest Lake | DTD | 3.1 | 0.3 |

What You Can Expect:



Radon Levels Before and After

| Install Date | Year Home Built | Address | City | Type of Mitigation | Pre-Mitigation Result | Post-Mitigation Result |
|---|-----------------|--------------------------|----------------------|--------------------|-----------------------|------------------------|
| Jul-19 | 1992 | Vivian Ave | Shoreview | DTD | 3.9 | 0.3 |
| Jul-19 | 1965 | Quebec Ave S | Golden Valley | DTD | 5.0 | 0.3 |
| Jul-19 | 2008 | Enfield Ave N | Hugo | DTD | 3.1 | 0.3 |
| Aug-19 | 1976 | Lily St NW | Coon Rapids | SSD | 2.6 | 0.3 |
| Oct-19 | 1926 | Franklin Ave SE | Minneapolis | SSD | 6.0 | 0.3 |
| Nov-19 | 1971 | Argon St | Andover | SSD | 6.9 | 0.3 |
| Dec-19 | 1986 | Joplin Way | Lakeville | DTD | 3.4 | 0.3 |
| Jan-20 | 1969 | 34 th Ave N | Crystal | SSD | 6.4 | 0.3 |
| Jan-20 | 2007 | Penfield Ave N | Stillwater | DTD | 4.1 | 0.3 |
| Mar-20 | 1994 | 167 th Ave NW | Ramsey | DTD | 5.0 | 0.3 |
| Dec-18 | 1973 | Spyglass Road | Dellwood | SSD | 7.2 | 0.4 |
| Jun-19 | 1994 | Novak Ave N | West Lakeland Twnshp | DTD/SSD | 5.8 | 0.4 |
| Feb-20 | 2005 | Maple Hurst Dr S | Rockford | DTD | 4.6 | 0.4 |
| Jul-19 | 2003 | Waco St NW | Anoka | DTD | 4.2 | 0.5 |
| Oct-19 | 1966 | Richmond Ave | Shoreview | DTD/SSD | 4.0 | 0.5 |
| Nov-19 | 1984 | Co Rd 30 | Elk River | SSD | 10.0 | 0.5 |
| Nov-19 | 2001 | 89th Place N | Maple Grove | DTD | 2.0 | 0.5 |
| Feb-20 | 1965 | Vicksburg Ln N | Plymouth | SSD | 4.6 | 0.5 |
| Feb-20 | 1967 | 131 st Ave NW | Coon Rapids | SSD | 9 | 0.5 |
| Jan-18 | 1996 | Lake Elmo Ave N | Stillwater | DTD | 2.2 | 0.6 |
| Aug-19 | 1882 | 11th Ave S | Minneapolis | SSD | 7.8 | 0.6 |
| Aug-18 | 1949 | Florida Ave N | Crystal | SSD | 12.0 | 0.7 |
| Mar-19 | 2014 | Heron Ln | Victoria | DTD | 4.6 | 0.7 |
| Apr-19 | 1955 | Manning Ave S | Afton | SSD/SMD | 12.8 | 0.7 |
| Jun-18 | 1956 | Clarmar Ave | Roseville | DTD | 4.5 | 0.8 |
| Jul-18 | 1950 | Iowa Ave | St Paul | SSD | 5.1 | 0.8 |
| Aug-18 | 1968 | Terrace NW | New Brighton | DTD | 13.0 | 0.8 |
| Aug-19 | 1992 | Rabbit St NW | Zimmerman | DTD | 5.6 | 0.8 |
| Nov-19 | 1905 | Bay St | St Paul | SSD | 2.4 | 0.9 |
| Dec-19 | 1989 | Doral Road | St Paul | DTD | 3.3 | 1.5* |
| Jan-18 | 1974 | 1 st St S | Buffalo | SSD | 21.4 | 1.6** |
| Jan-18 | 1952 | 88 th Ave NW | Coon Rapids | SSD | 9.0 | 1.6** |
| Dec-19 | 1941 | Polk St | Minneapolis | DTD | 10.0 | 2.8*** |
| Average Post Mitigation Radon Level Since 2018 | | | | | | 0.4 |

*Sub-slab ductwork (HVAC below the concrete floor) has leaks. Duct sealing recommended.

**Additional suction point recommended.

***Basement was mitigated. Crawl space was not elected to be mitigated and has HVAC return ducts that draw radon into home. Crawl space encapsulation recommended.

Type of Mitigation Key:

SSD – Sub Slab Depressurization
 DTD – Drain Tile Depressurization
 SMD – Sub Membrane Depressurization